# PERSONNEL QUALIFICATIONS



## **Peter S. Nelson** | Associate Principal and Unit Manager



#### **EDUCATION**

- University of Illinois at Urbana-Champaign
  - Bachelor of Science, Civil Engineering, 2006
  - Master of Science, Civil Engineering, 2008

#### **PRACTICE AREAS**

- Repair and Rehabilitation Design
- Failure Investigation
- Structural Evaluation
- Facade Assessment

### **REGISTRATIONS**

- Professional Engineer in IL
- Structural Engineer in IL

## **PROFESSIONAL AFFILIATIONS**

- American Concrete Institute
- International Concrete
  Repair Institute

#### CONTACT

pnelson@wje.com 847.272.7400 www.wje.com

#### **EXPERIENCE**

Since joining WJE in 2009, Peter Nelson has gained experience in condition assessment, structural evaluation, and repair and rehabilitation design. He has investigated multiple failures involving concrete, wood, masonry, and steel structures. Mr. Nelson also has experience with various facade evaluation and repair projects, including concrete, masonry, and glass and aluminum curtain wall systems.

Before joining WJE, Mr. Nelson conducted undergraduate and graduate-level research at the Army Corps of Engineers research facility in Champaign, Illinois. His research focused primarily on testing wood shear panel walls and large-scale shake-table testing.

#### REPRESENTATIVE PROJECTS

## **Repair and Rehabilitation Design**

- Soldier Field Chicago, IL: Condition assessment of historic concrete structure, repair design, and construction period services
- 1630 Sheridan Road Wilmette, IL: Repair design and construction period services for below-grade parking structure and entry plaza repair project
- Ryan Field Evanston, IL: Structural repair design and construction period services for multiple concrete repair projects
- The Waterford Chicago, IL: Condition assessment and construction period services for balcony repair project
- Wheaton Center Wheaton, IL: Condition assessment, repair design, and construction period services for high-rise residential buildings and parking structures
- Optima Views Evanston, IL: Construction period services for green roof plaza restoration atop parking structure
- 1630 Sheridan Road Wilmette, IL: Repair design and construction period services for balcony repair project

#### **Failure Investigation**

- Christensen Farms and Feedlots Weldon, IA:
  Field investigation and evaluation of timber truss roof collapse
- Boston Store Wall Collapse Milwaukee, WI: Field investigation and evaluation of masonry wall failure

 Shure Headquarters - Niles, IL: Field investigation and evaluation of sunshade failure

#### **Structural Evaluation**

- Byron Nuclear Generating Station, Hyperbolic Shell Cooling Towers - IL: Structural condition assessment of two 500-foot-tall natural draft cooling towers
- Edwin I. Hatch Nuclear Plant Baxley, GA:
  Structural monitoring program inspections for maintenance rule and license renewal
- Port of Houston Authority TX: Condition assessment for multiple wharf structures
- LaGrange Fire Station LaGrange, IL:
  Structural assessment of existing concrete framing
- Larimer County Fairgrounds Loveland, CO: Structural evaluation and design of roof framing repairs
- Byron Nuclear Generating Station, Essential Service Water Cooling Tower - IL: Structural assessment of safety-related cooling tower in support of license renewal
- 1630 Sheridan Road Wilmette, IL: Structural assessment of seawall structure

#### **Facade Assessment**

- University of Phoenix Stadium Glendale, AZ: Investigation of wind-related effects on composite cladding panels
- Various evaluations of glass surface distress resulting from construction activities, cleaning processes, and natural disasters
- One East Wacker Street Chicago, IL: Investigation of marble facade distress, repair design, and construction period services
- 135 South LaSalle Street Chicago, IL: Limestone facade examinations and repair period services
- InterContinental Hotel Chicago IL:
  Construction period services to address limestone parapet distress
- One South Wacker Street Chicago, IL: Facade examinations and construction period services
- 400 North LaSalle Street Chicago, IL: Condition assessment and construction period services to address concrete facade distress

